Chairman

Robert Beedle- Council Rep.

Vice-Chairman

Greg LoForte

Commission Members

Brent Davis

Mike Adams

Max Wiese

OF CORDOLLY

HARBOR COMMISSION REGULAR MEETING 10/12/2011 7:00:00 PM CITY HALL CONFERENCE ROOM

Harbormaster

Dale Muma

AGENDA

A. CALL TO ORDER

Secretary

Brandy Griffith

B. ROLL CALL

Brent Davis, Greg LoForte, Robert Beedle, Mike Adams, Max Wiese

C. APPROVAL OF AGENDA

D. COMMUNICATIONS BY VISITORS

E. APPROVAL OF MINUTES

1. Regular meeting of 9/14/11

F. HARBORMASTER'S REPORT

G. CORRESPONDENCE

H. OLD BUSINESS

I. NEW BUSINESS

1. Harbor Facilities/Uplands Master Plan

J. AUDIENCE PARTICIPATION

K. COMMISSION COMMENTS

L. ADJOURNMENT

Harbor Commission Regular Meeting Wednesday, September 14, 2011 at 7:00 PM City Hall Conference Room

- A. Call to Order. The meeting was called to order by Vice -Chairman Greg LoForte at 7:05.
- B. Roll Call. In Attendance: Greg LoForte, Mike Adams, Max Wiese, Harbormaster Dale Muma, and recording secretary Brandy Griffith.
- C. Approval of Agenda. M/Wiese, S/Adams, V/ Unanimous to approve the agenda.
- D. Approval of previous minutes. M/Wiese, S/Adams, V/ Unanimous to approve the minutes of July 13, 2011.
- E. Communications by Visitors: None
- F. Harbormaster's Report. Harbormaster Muma reported approval of funding for the removal of the Sound Developer. There is no change in the status of the land trade with Samson or the Chugach Corp.
- G. Correspondence: None
- H. Old Business: City boat storage / Lots 3A, 4 & 5 of Block 8 North Containment Area. Reviewed proposed maintenance/storage area rules. Motion to approve rules as written by Wiese, S/Adams, V/ Unanimous to approve rules.
- 1. New Business: 2012 Harbor Rates/ Fees Recommendation. Reviewed proposed 2012 Rates/ Fees. M/Adams, S/Wiese, V/Unanimous to approve rate/ fees recommendation as written.
- J. Audience Participation. None
- K. Commission Comments:

Wiese: Glad to see Sound Developer is finally getting removed.

Adams: Glad to see Breakwater project is going to be completed by local contractors.

L. Adjournment: M/LoForte, S/Adams, V/Unanimous

HARBORMASTER'S REPORT OCTOBER 2011

- 1. Nothing new to report on the progress of the USCG letting the contract for the removal of the Sound Developer. I have had conversations with a few of the contractors who will be bidding on the job and it sounds like they are planning on cutting up and removing the boat once it gets beached and accessible. I also spoke with Chris Meade of the EPA who talked about scuttling the boat. He said it is possible to get a permit although expensive. I reported that it appears the contractors are headed in a different direction than the scuttling option.
- 2. Meeting dates for the remainder of the year are 11/9 and 12/14.
- 3. I have submitted the 2012 budget which includes the cost for improvements to the North Containment storage area to include utilities for a small maintenance area. If approved, I will begin notification of users regarding the new use policy and make preparations to have utilities installed sometime next spring/summer.

MEMO

DATE: October 4, 2011

TO: Harbor Commission

FROM: Harbormaster Muma

RE: Harbor Master Plan

Attached is a rough draft of the Harbor Facilities/Uplands Master Plan. As stated on the cover page of the plan, the purpose of this document is to provide direction for the future maintenance, use and development of harbor facilities and the immediate uplands. The plan has three sections, one each for Facilities, Expansion and Uplands. I have provided a brief history of each facility and have taken the responsibility of suggesting maintenance and development needs for future use. There will need to be some discussion regarding uplands and your recommendation for future needs. I have provided my opinion for harbor expansion but of course your recommendation can be included as well.

Keep in mind that this is just a rough draft and your comments, changes and suggestions are welcome and encouraged. We can spend as many meetings as needed to develop this plan to the point where it will be ready to submit to the city council for their consideration. I will leave it up to this commission to decide the best way to evaluate this draft.

CITY OF CORDOVA HARBOR FACILITIES/UPLANDS MASTER PLAN (Rough Draft)

The purpose of this document is to provide the Harbor Commission, city council, city administration and city staff direction for the future maintenance, use and development of the Cordova Harbor facilities and the immediate adjacent harbor area uplands. Recommendations in this document will be developed by the Harbor Commission and harbor staff as a long-term plan and will be presented to the Cordova City Council upon its completion.



Prepared by Cordova Harbor Dept., 2011

FACILITIES

OLD HARBOR – Originally constructed in 1938, this facility was re-built following the 1964 earthquake. In 2005, after 41 years, this facility was completely renovated using funds received from the State in a transfer of ownership agreement which gave the City full ownership of the entire harbor. This facility is constructed using wooden floats, supported by steel piles and has the capacity to moor 214 vessels. **Current condition: Excellent**

Future Needs Within:

- ❖ 5 Years Minor maintenance
- ❖ 10 Years Minor maintenance/limited replacement of float components such as bullrails, decking, utilities where necessary.
- ❖ 20 Years- Maintenance to major components becomes more significant and frequent. Ongoing replacement of floats, decking, utilities should continue. Discussion regarding renovation should begin as this facility will be 26 years old.

LOADING DOCK – This facility was also rebuilt following the 1964 earthquake. The decking was replaced in 1998 and again in 2010. The old gantry style hoist was removed in 2010 and replaced with a hydraulic hoist. There are no known problems with existing piling or bracing. **Current condition: Good**

Future Needs Within:

- 5 Years- Replacement of decking where needed.
- ❖ 10 Years- Evaluation of support piles and bracing. Replacement of all decking.
- ❖ 20 Years-Evaluation of entire facility for useful life remaining.

OLD GRID- This facility is a 180'/90 ton wooden grid which was constructed following the 1964 earthquake. It has had some replacement of timbers in the early 90's but no other maintenance. Several of the supporting piling are rotten. The Harbor Department placed a vessel length limit of 50' on this facility in the late 1990's to help reduce damage. The trestle and dock associated with this grid have had some minor piling repair and bracing replacement. The building on this dock is currently being used as offices for the Prince William Sound Science Center. It has had extensive repairs and upgrades but is an old structure and should be evaluated in the future to determine if it retains any useful life. The deck to this trestle was replaced in 1998. **Current condition: Grid-**

Poor to Fair, Trestle-Fair

- ❖ 5 Years-Replacement of grid timbers and trestle decking as needed.
- ❖ 10 Years-Evaluation of entire facility including the building. Based on the evaluation of the facility, decide whether to close and remove entire facility including grid, trestle, dock and building. This area could be used as a location for future expansion of harbor facilities. Possibilities include a new grid, more slips,the extension of the Old Harbor Loading Dock.
- 20 Years-Construction of a new facility in this area.

OLD HARBOR APPROACH #4- This facility was constructed following the 1964 earthquake and the only maintenance performed has been decking replacement. During the renovation of the Old Harbor in 2005, this approach had a complete decking replacement. The building on this approach, although appears to be in fair condition, is approximately 46 years old. To eliminate future maintenance, this structure should be removed once it has reached the end of its useful life. The gangway on this approach was installed during the 2005 renovation and is in excellent condition. Current condition: Good

Future Needs Within:

- ❖ 5 Years- Replacement of all decking.
- Years- Evaluation of all decking, support piles and bracing and replace as needed. Evaluation of building and removal if necessary. Evaluation of gangway and repair where necessary.
- ❖ 20 Years- Evaluation of support piles, bracing and replace as needed. Replacement of all decking. Evaluation of building (if still in existence) and removal if necessary. Evaluation of gangway and repair where necessary.

OLD HARBOR APPROACH #5- This facility was constructed following the 1964 earthquake and the only maintenance performed has been decking replacement. The decking was replaced in 1998 and again in 2010. The gangway on this approach was installed during the 2005 renovation and is in excellent condition. **Current condition: Good**

Future Needs Within:

- ❖ 5 Years-Continued replacement of decking as needed.
- Years- Evaluation of all decking, support piles and bracing and replace as needed. Evaluation of gangway and repair where necessary.
- ❖ 20 Years- Evaluation of entire facility for remaining useful life.

NEW HARBOR-This facility was constructed with the expansion of the harbor beginning in the early 80's. It is currently 27 years old. This is primarily a concrete float facility with wooden components to tie it together. The transient float is wood with steel piles. The remainder of the harbor has a combination of wood and steel piles. Although the concrete in this facility has held up very well, we are starting to see the wooden components beginning to fail. The waterline was replaced in the mid-90's with an HDPE line which, since its introduction, has required very little maintenance. Electrical components have had to be replaced at frequent intervals. H and I Floats have experienced significant damage due to winter storms which produces a swell which enters the harbor uninterrupted. In 1994, the State of Alaska spent approximately \$100,000 repairing damage from the north wind. Since that time, the harbor has seen the loss of several more finger floats due to the same north swells. This harbor has the capacity to moor 501 vessels. This facility should provide another 10-15 years of reliable service. Current condition: Fair to good

- 5 Years-Continued replacement of and maintenance to structural components and utilities. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- ❖ 10 Years-Continued replacement of and maintenance to structural components and utilities. Efforts to secure funding for facility replacement should be in progress.
- 15 Years-Replacement of facility.

NEW GRID-This facility is a 160'/250 ton steel grid and was constructed during the harbor expansion of the early 80's. During the first twenty years of its existence, this facility required frequent replacement of the wooden timbers. The last complete replacement of the wooden components was in 1997. In 2006, all of the wooden timbers were replaced with HDPE. Since that time, no maintenance has been required at this facility. **Current condition: Very good**

Future Needs Within:

- 5 Years-Monitor silt accumulation around lower grid bents and remove as necessary.
- ❖ 10 Years- Monitor silt accumulation around lower grid bents and remove as necessary. Complete an evaluation of all grid components, including steel piling, catwalk and HDPE timbers and replace items where necessary.
- 20 Years- Monitor silt accumulation around lower grid bents and remove as necessary. Complete an evaluation of all grid components, including steel piling, catwalk and HDPE timbers and replace items where necessary.

NEW HARBOR APPROACH #1-This facility was constructed during the New Harbor construction of the early 80's. Since that time, no maintenance or repairs has been required at this approach. **Current condition:** Good

Future Needs Within:

- 5 Years-Replace planks and bullrails as needed.
- ❖ 10 Years- Continued replacement decking where needed. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- 4 15 Years- Replacement of facility.

NEW HARBOR APPROACH #2- This facility was constructed during the New Harbor construction of the early 80's. Since that time, no maintenance or repairs has been required at this approach. **Current condition:** Good

- ❖ 5 Years-Replace planks and bullrails as needed.
- ❖ 10 Years- Continued replacement decking where needed. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- 15 Years- Replacement of facility.

NEW HARBOR APPROACH #3- This facility was constructed during the New Harbor construction of the early 80's. Since that time, no maintenance or repairs has been required at this approach. **Current condition:** Good

Future Needs Within:

- 5 Years-Replace planks and bullrails as needed.
- ❖ 10 Years- Continued replacement decking where needed. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- 15 Years- Replacement of facility.

NEW HARBOR/NEW GRID APPROACH - This facility was constructed during the New Harbor construction of the early 80's. Since that time, no maintenance or repairs has been required at this approach. **Current condition:** Good

Future Needs Within:

- ❖ 5 Years-Replace planks and bullrails as needed.
- ❖ 10 Years- Continued replacement decking where needed. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- ❖ 15 Years- Replacement of facility.

THREE STAGE DOCK- There was major modification and enhancement of this facility during the New Harbor expansion of the early 80's. Since that time, the decking has been replaced on all levels of this dock, bullrails have been replaced, and all sway bracing under the dock has been replaced as well. Current condition: Good

Future Needs Within:

- ❖ 5 Years-Replace planks and bullrails as needed.
- ❖ 10 Years- Continued replacement decking where needed. Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- ❖ 15 Years- Replacement of facility.

INNER HARBOR LAUNCH RAMP- This facility was constructed in 2005 with the renovation of the Old Harbor. This launch ramp also includes an access float. Since its construction, no maintenance has been necessary. **Current condition: Excellent**

Future Needs Within:

- ❖ 5 Years-Continued monitoring of concrete planks on ramp and articulated access float. Make repairs/maintenance as needed.
- ❖ 10 Years- Continued monitoring of concrete planks on ramp and articulated access float. Make repairs/maintenance as needed.
- 20 Years- Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.

NORTH FILL LAUNCH RAMP- This facility was constructed in 1990 and has seen considerable damage to concrete planks due primarily to landing craft use. Although still usable, this facility needs improvement work. In 2011, funds were approved by the State of Alaska in the amount of \$350,000 for launch ramp improvements. Initial estimates by

city engineers report that approximately \$800,000 will be needed to construct and install an access float at this ramp. Current condition: Fair

Future Needs Within:

- 5 Years- Complete an evaluation of facility condition with preliminary design and cost estimate for facility replacement.
- ❖ 10 Years- Continued monitoring of facility for repairs and maintenance. Secure funding and replace facility.
- 20 Years- Continued monitoring of facility. Make repairs/maintenance as Needed.

NORTH CONTAINMENT BOAT STORAGE AREA- Since the creation of this fill, these three lots just north of Bayside Storage have been used as a city boat storage area. It has been re-organized once and the Harbor Dept., along with the Harbor Commission, is currently developing plans and rules for use of this area to make it more user friendly by the addition of a maintenance area with water and power beginning in 2012. Current condition: Good

Future Needs Within:

- ❖ 5 Years- Completion of maintenance area including vessel spaces with water and electricity available at each space. Continue monitoring by harbor staff to ensure proper use.
- ❖ 10 years- Maintenance to utilities as needed. Continued monitoring by harbor staff to ensure proper use.
- ❖ 20 Years- Maintenance to utilities as needed. Continued monitoring by harbor staff to ensure proper use.

CITY DOCK- Constructed in 1965, this facility was the moorage facility for the USCG buoy tenders until 2002 when the USCG relocated to the North Fill T-Dock. This dock was completely re-decked in 1998 and then underwent a 4 million dollar renovation in 2005. This renovation included piling replacement, decking and bullrail replacement, installation of fenders and camels, installation of dolphins, upgraded lighting and replacement of all sway-bracing. Since the renovation only minor maintenance has been required to the camels and lighting. Current condition: Excellent

Future Needs Within:

- ❖ 5 Years Monitoring of facility for needed repairs and maintenance.
- ❖ 10 Years- Continued monitoring of facility for repairs. Decking will most likely need replacement. Camel anchoring system should be evaluated and replaced as needed.
- ❖ 20 Years-Continued monitoring of facility. Replacement of all decking and bullrails. Replacement of sway-bracing where needed. Replacement of camels and anchoring system. Upgrade/replacement of lighting system.

NORTH CONTAINMENT T-DOCK- This facility was constructed in 1989 and was initially used for loading and unloading of fishing gear and light freight. In 2002, extensive upgrades were completed as part of an agreement with the USCG to relocate their new buoy tender to this facility. This is a secure facility and is leased to the USCG for buoy tender moorage. This facility is a concrete dock supported by steel piles. It has

a timber fender system as well as a series of camel logs which keeps the buoy tender off the face of the dock. Since the upgrade, little maintenance has been required at this facility. One fender was replaced due to a vessel strike and there have been some waterline problems during the winter months. The abutment between the dock approach and the road was replaced with a concrete one in 2011. **Current condition: Excellent**

Future Needs Within:

- ❖ 5 Years- Monitor fenders, camels and lighting for needed maintenance.
- 10 Years- Evaluation of steel piles for corrosion and installation of cathodic protection if necessary. Monitor fenders, camels and lighting for needed maintenance.
- ❖ 20 Years- Continued monitoring of all facility components for repairs.

MUNICIPAL DOCK(Ocean Dock)- This is Cordova's primary facility for the reception of the community's fuel and waterborne freight. This dock, constructed in 1968, is a concrete facility supported by steel piles. A brief history of maintenance at this facility is as follows: 1982- Replacement of all fenders on the face of the dock. 1994-Installation of heat shrink wraps to all piling to enhance corrosion protection. 1997-Bullrail repair/replacement at the face of the dock. 2001- Piling cluster re-securement at dock corners. There is a small building of the dock which houses the Cathodic Protection system which provides a steady current to all piling to prevent corrosion. This system is inspected and serviced every year and is in good operating condition. This facility, for its age, is generally in good condition. I credit the condition of the dock to less use over recent years. Samson Tug & Barge and Shoreside Petroleum are the only regular users. In the past other users included Sealand, and the Alaska Marine Highway. Sealand no longer comes into Cordova and the Marine Highway constructed their own facility in 2005. Upgrades to components of the dock need to be considered to extend the life of the facility. Current condition: Good

Future Needs Within:

- ❖ 5 Years- Continued maintenance to bullrails, fenders, overhead lighting and cathodic protection. Although these components are starting to show their age, with proper repairs should last at least five more years.
- 10 years- Funding should be secured to begin replacement of all bullrails, fenders (especially at dock face) and lighting. The cathodic protection system should be evaluated for life expectancy and either be updated or replaced.
- 20 years- A thorough evaluation of this facility should be completed to Determine remaining useful life.

TRAVEL LIFT FACILITY- Construction to this facility was completed in 2010. It includes the Marine Travelift, piers, washdown pad, water treatment unit, maintenance area including overhead lighting and utilities. The facility operates on approximately 2 acres of the Ocean Dock Subdivision. The Marine Travel Lift was purchased in 2009. The City is currently negotiating with Samson Tug & Barge to make a property trade to make the travel lift facility and operating area more efficient. Current condition: Excellent

- ❖ 5 Years- Explore options and secure funding to expand existing fill to provide for additional space for vessel maintenance/storage and to provide space to erect a large maintenance building.
- Years- Expand fill and erect maintenance building. Monitor facility, equipment and systems for continued maintenance and repairs.
- ❖ 20 Years- Continued maintenance to all facilities, equipment and systems.

UPLANDS

SOUTH CONTAINMENT FILL- Since its construction during the early 80's harbor expansion project, this area has reached its capacity for future development. The possibility of expansion of this area needs to be discussed. Other discussion should include parking, sidewalks and use and direction of future expansion.

Future Needs/Discussion Items: 1. 2. 3. 4. 5. 6. 7.

NORTH CONTAINMENT FILL- Since its construction during the early 80's harbor expansion project, this area has reached its capacity for future development. The possibility of expansion of this area needs to be discussed. Other discussion should include parking, sidewalks and use and direction of future expansion.

Future Needs/Discussion Items:

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.

HARBOR EXPANSION

The future expansion of the harbor is a topic that has been discussed recently since slips for boats larger than 40' have been in demand for approximately the last year. Due to damage from the north wind, the harbor experienced the loss of three more 50' finger floats during the winter of 2010/2011. Since the last expansion in the early 80's, winter storms have caused the loss of 7-50' finger floats(14 slips) and 3-30' finger floats(6 slips). The loss of the smaller slips is insignificant, however, the loss of the 50' slips has proven to put a demand for large boat moorage on the harbor. Although discussion of expansion is certainly a valid topic, there may be ways to avoid this expensive endeavor. At some point in the next 10-15 years, the New Harbor will have to be renovated as it will be approaching the end of its useful life. With thoughtful design and engineering, the New Harbor renovation should provide adequate moorage for years to come. With input from city staff, Harbor Commission and the public, engineers should be able to design a more efficient, user friendly harbor layout that will sufficiently provide moorage for the fleet. Since about 1990, the annual stall rental capacity has fluctuated anywhere from 70% to as high as 88%. With a more efficiently designed harbor, the ability to accommodate all users should not be an issue.

Possible future expansion into the area that is now occupied by the Old Grid and the Prince William Sound Science Center could also provide for additional slips as well. This area could provide for several large boat slips or as many as twenty small boat slips.